OREGON CORNER RESTORATION FORM				<u> </u>
Section County	7Township UmatillaDate:	December 24, 2009	32E	_
Corner De	esignation: 1N32G5			Condition Report Only Not found
Quarter corner common to sections 7 and 8, T1N, R32E, W.M., Umatilla County, Oregon.			x	_Remonumented Unrecorded _Surveyed in
	Renewals / Surveys, etc		X	_Referenced out

Corner originally set by Daniel Chaplin under contract No. 107 Dated September 21, 1864. His record reads: Set post for 1/4 sec. corner in mound of earth, with charred stake, pits, &c, as per instructions.

Monument and Accessories found: (condition and source) None. The point falls in a plowed field.



I set a 1" x 24" iron rebar with a 2" aluminum cap stamped as shown in the diagram above at the proportioned point. The rebar is driven 14" into the bedrock and the cap is 20" below the surface of the field.

For references, I set four 5/8" by 24" iron rebars with 1 1/4" orang plastic caps stamped WTS and 56295LS as described below:

an iron rebar bears N38°11'30"W, 53.36 feet in the existing fence; an iron rebar bears N45°50'55"E, 44.74 feet 20 inches below the surface of the field; an iron rebar bears S53°34'50"E, 53.33 feet 20 inches below the surface of the field; an iron rebar bears S36°31'26"W, 58.22 feet in the existing fence;

This monument was set and references tied using a Trimble R7/R8 RTK GPS system.

Location and comments	Compass Declination	Surveyors Seal
NAD 83/1991 State Plane Cool	dinate	•
Oregon North Zone		REGISTERED
N = 702,003.97 ift		PROFESSIONAL
E = 8,624,902.03 ift		LAND SURVEYOR
	Firm / Agency	Entre Contrelion
	Witness Tree Surveying	Stephen K. Halbal
RECEIVED BY:	Address	OREGON
Umatilla County Surveyor	P.O. Box G	JULY 9, 2001
Date: 6-10	Pilot Rock, Or. 97868	STEPHEN K. HADDOCK
Rec'd By: KF	Party Chief	56295LS
No. 10-93-6	Stephen K, Haddock	RENEWAL DATE 6- 30-11