OREGON CORNER RESTORATION FORM

Section: 15

Township: 4 North

Range: 37 East, W.M.

County: Umatilla

Date: 06/22/2000

Corner Designation: K-17, North 1/16 corner on the East line of Section 15, applies to Section 15 only

Previous Renewals/Surveys, etc.: None

Monument(s) & Accessories Found (Condition & Source): None

Monument Detail: T4N R37E

S15+

N 1/16

2000

LS 2820

. .

Monument Set (Procedures & Description): At the position determined by survey, cemented a 2" brass disc in a drill hole at the base of a 12' high rock bluff,

New Accessories: Set 6' steel fence post 3' Northeast of the corner. A 16" Douglas fir bears N50°E 21.2 feet marked N1/16 S15 BT. A 15" Douglas fir bears S90°E 22.3 feet marked N 1/16 S15 BT. A 1" long "MAG" nail in a ½"x ½" drill hole 3" above the ground in a 3'x 3' rock face bears S12°E 2.6 feet. A 24" Douglas fir bears N69 1/2°W 64.4 feet marked N 1/16 S15 BT.

All bearing trees have a 6" wide red band painted around them and bearing object signs attached. The bearing object is painted red and has a bearing object sign attached.

Location & Comments: This corner is located on a steep Northeasterly facing slope at the base of a 12' high rock bluff 800'± South of the South Fork of the Walla Walla River.

Compass Declination: 19° East

Firm/Agency: Tomkins Land Surveying, Inc. 20 E. Poplar, Suite 204 Walla Walla WA 99362

Party Chief: Greg Flowers Notes: Greg Flowers Witness: Ryan Laughery Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR lowers OREGON JUNE 30, 1997 GREG E. FLOWERS 02820LS RENEWS 12/31/01 12/15/00

EBCEIVED BY Usuatilla County Surveyor Date <u>12-00</u> Bao'd By <u>5/4</u> Bao'd By <u>5/4</u>