OREGON CORNER RESTORATION FORM

Section 6 Township 5S Range 31E
County Umatilla Date: 11-28-01

Corner Designation: 5S31A1

_____	Condition Report Only
_____	Not Found
_____	Remonumented
_____	Unrecorded
____x____	Surveyed In
_____	Referenced Out

Previous Renewals / Surveys, etc.

Under Special instructions dated May6, 1957, Craig Wanless of the BLM replaced the original stone with a BLM brass cap stamped as shown in the diagram. He set two new bearing trees;

A ponderosa pine, 9 ins. daim., bears N.34°E., 27 1/2 lks. dist., mkd T4S R31E S31 BT. A ponderosa pine, 11 ins. diam. bears S. 52 1/2°E., 31 lks. dist., mkd T5S R31E S6 BT.

Monument and Accessories Found: (condition and source)

Found the brass cap as described. Found: A sawed pine stump N50°E, 35.6'; a sawed pine stump S33°E, 77.9'; a 21" ponderosa pine S70°W, 25.7'; a high stumped 29" pine bears N80°W, 52.8'; a 10" ponderosa pine bears N34°E, 18.2'; a 12" ponderosa pine bears S52 1/2°E, 20.5'

DIAGRAM



SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None

Made GPS tie to TRI Station FORE.
Latitude 45°10'12.30887"N
Longitude 119°01'26.37795"W
NAD 83(1991)

Oregon State Plane Coord. - North Zone
Northing 551580.28
Easting 8582726.03
Ortho Height 4105.27
Ellipsoidal Height 4045.24

Location and Comments

From junction Highways 395 and 244, go west on FS Road 53 3.5 miles to north south fence. Walk along fence north 1.3 miles to corner.

Compass Declination

20°E

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-03

RECEIVED BY:

Date: 01-02
Rec'd By: KC
No. 02-04-R

Firm / Agency

Haddock Surveying
P. O. Box 1574
Pendleton, OR 97801
(541) 276-2174