

BASIS OF BEARINGS THIS SURVEY WAS PERFORMED IN THE STATE PLANE SYSTEM OREGON NORTH NAD83/91.

지 것 이야지는 그 것이 없는 것, 그의 것 이야지는 데이지가 가지 않는 것을 하는 것을 해보여야 한다. 사람이 가지 않아야 한 것은 것 같이 않는 것 같이 없다.

REGISTERED

PROFESSIONAL

LAND SURVEYOR

OREGON

JULY 9. 2001 STEPHEN K. HADDOCK

56295LS

RENEWS 6-30-17

res services reactions and a service of the service of the service services of the first service for the first The service of the service of the service of the service services and the services of the service of the servic

BEARINGS SHOWN ON THIS MAP ARE BASED ON GPS OBSERVED GRID BEARINGS ROTATED 0 *55 49" CLOCKWISE TO TRUE BEARINGS. GROUND DISTANCES SHOWN WERE OBTAINED BY APPLYING A COMBINED SCALE FACTOR OF 0.99992719 TO THE GRID DISTANCES.

RECEIVED BY Umatilla Çounty Surveyor Date: ///01/20/6 Rec'd By: m. 16-100-B No.:

SHEET OF 1

SURVEY FOR	PROJECT DATE: August 16, 2016				
Mr. William Hensal 33480 Collins Lane Stanfield, OR 97875	Project No. 16-19	SCALE: 1" = 500'			
	WITNESS TREE SURVEYING Stephen K. Haddock, PLS, CFedS				
LOCATION: East 1/2, Section 28, T4N, R29E, W.M., Umatilla County, Oregon.	P.O. Box G Pilot Rock, Oregon 97868 (541) 443-2922				



· 通知的 新闻的 医结核性 医肾上的 医鼻子 化合理机 医脊髓管 化合理的 医鼻子的 医子宫 化化学管理 事件。

NARRATIVE OF SURVEY Continued from Sheet 1

The Hensal properties, and those around them, were cut out of the Inland Irrigation property between 1911 and 1915. The date of creation of each property and the recording reference for each deed of origin is given on this map. It should be noted that Mr. S.J. Moore purchased Tax Lot 700 in 1914 and Tax Lots 400 and 1500 in 1915. Mr. Moore subsequently sold Tax Lot 400 in 1916, Tax Lot 700 in 1919, and lost Tax Lot 1500 for taxes to Umatilla County in 1922, leaving the order of junior-senior rights unchanged.

Current descriptions for all of these properties are the same as the original except for Tax Lot 600. The original descriptions of the Carr properties used the term "more or less" on all of the bearings and distances cited in the Carr deeds. This term was dropped in 1932 by the Sheriff's deed in Book 141, Page 577 which also changed the lengths of the south lines of Tax Lot 600 from 710' and 307' to 711' and 306' respectively. I have held the original deed dimensions.

There is an overlap of Tax Lot 400 onto Tax Lot 300 and of Tax Lot 1500 onto Tax Lot 700. Both of these overlaps were created in 1915 by the deed to S.J. Moore in Book 90, Page 319. In both cases, I have resolved the overlap in favor of the senior title. The overlap of Tax Lot 1500 onto Tax Lot 700 was called out in the deed recorded in Book 196, Page 267 as an exception to title. That deed erroneously stated that the overlap was created by the Sheriff's Deed in Book 141, Page 577. The extent of the overlap of Tax Lot 1500 onto Tax Lot 700 cannot be determined entirely since the point of beginning of the description on Tax Lot 1500 is based on the location of the east line of the Furnish Ditch Right of Way which likely has

wandered between 1915 and today. The deeds for Tax Lots 300, 400, west part of 600 and both parts of 700 all call for the center east 1/16th corner as the common point of beginning. Mr. Hensal stated that the prior owner, Mr. Emery Burke, had shown him the bolt at this corner and said to protect it as it was the property corner. Measurements from this bolt to the canal rights of way and the 1/4 corner to the east agree within reason (given the era that these descriptions were first created) that this bolt does mark the center east 1/16th and I have held it as being that point.

As stated above, the dimensions in the deeds to the Carrs were called "more or less". Holding the record bearings for Tax Lots 600 and 700 resulted in significant discrepancies in line lengths along the Feed Canal and also significantly increased the size of the overlap with Tax Lot 1500. Holding the record distances resulted in the greatest agreement with all descriptions involved. Overlaying the survey on a 1998 Ortho Rectified Aerial Photo obtained from the Umatilla County Assessor's Office confirms that the line produced by holding the record distances follows the long term possessory line in this area. I have therefore held the record distances over the record bearings.

The Furnish ditch was rebuilt and realigned in 2008. The location of the old ditch as shown hereon is based on the information in survey 08-36-A. The location of the USRS Feed Canal as shown is based on my survey of the current canal centerline. The location of the Hensal boundaries is based on their deed. The canal right of ways as currently known are slightly different than the Hensal lines as described. The exact location of the canal right of ways and the extent of changes in them over time is beyond the scope of this survey.

This survey was performed with a Trimble R7/R8 RTK GPS system.

enterline ned by of current	N00 *00' 20 "E 1324.09'	 LEGA SET 5/8"X24 WITH ORANGE STAMPED WTS FOUND BRASS SURVEY 95-6 FOUND 1/2" IDENTIFIED AS ONLY KNO CORNER. COMPUTED PO XX.××-D RECORD DIME DEEDS 	TIC CAP 6295LS 98-213-C. 0LT DOWNERS PERTY		REGISTERED PROFESSIONAL LAND SURVEYOR UPA K. HADDOCK JULY 9, 2001 STEPHEN K. HADDOCK 56295LS RENEWS 6-30-17 HEET 2 OF 2			
TEE S RSON AL S BROS. ER				SURVEY FOR Mr. William Hensal 33480 Collins Lane Stanfield, OR 97875				
				LOCATION: East 1/2, Section 28, T4N, R29E, W.M., Umatilla County, Oregon.				
	527 16th	PROJECT DATE: August 16, 2016				, 2016		
01,		RECEIVED BY Umatilla County Surve	vor	Project No.	16-19	SCAL	E: 1" = 200	•
Date://_0/_20/L Rec'd By: <u>/6-/00-B</u> No.: 		WITNESS TREE SURVEYING Stephen K. Haddock, PLS, CFedS P.O. Box G Pilot Rock, Oregon 97868 (541) 443-2922						