OREGON CORNER RESTORATION FORM	
Section <u>3</u> Township <u>1N</u> Rang County <u>Umatilla</u> Date: <u>April 1, 2010</u>	e32E
Corner Designation: 1N32A17	x Condition Report Only
Corner common to sections 34 and 35, T2N, R32E, an sections 2 and 3, T1N, R32E, W.M., Umatilla County, Oregon.	d Remonumented d Unrecorded Surveyed in Referenced out

Previous Renewals / Surveys, etc.

Corner originally set by David P. Thompson under contract No. 106 dated August 16, 1864. His record reads:Set stone 24x15x10 ins. for corner to sec. 2, 3, 34 & 35. Zenas Moody, under contract No. 164, dated October 4, 1871 states: Set stone 18x14x12 for cor. to sec. 2, 3, 34 and 35. James Currin and James Noland in special instructions dated May 4, 1887 found the old mound and pits and state: Set basalt stone, 18x12x12 in old mound, marked 2 notches on E. and 4 notches on W. edges.

Monument and Accessories found: (condition and source) None. This point falls in the McKay Reservoir.



SKETCH

Monument and Accessories set:

None. This certificate is prepared to provide the state plane coordinates only.

 Location and comments
 Compass Declination

 NAD 83/1991 State Plane Coordinates

 Oregon North Zone.

 N = 710,249.31 ift

 E = 8,640,578.76 ift

 Firm / Agency

 Witness Tree Supervise

RECEIVED BY: Umatilla County Surveyor Date: @~10 Rec'd By: KK No. 10~93-C- Firm / Agency Witness Tree Surveying Address P.O. Box G Pilot Rock, Or. 97868 Party Chief Stephen K, Haddock Surveyors Seal

1	REGISTERED
1	PROFESSIONAL
L	LAND SURVEYOR
0	Toplan K. Hallock
-	
	OREGON JULY 9, 2001
	STEPHEN K. HADDOCK
1	56295LS
TR	ENEWAL DATE 6-30-11