OREGON CORNER RESTORATION FORM						
Section County	5_ Umatilla	Township	<u>1N</u>	Range	32E	
County	Umatilia	Date:	August 31,	2009		Condition Bonort Only
Corner De	esignation:	1N32E9				Condition Report Only Not found
					X	Remonumented
Corner common to sections 4, 5, 8, and 9, T1N,						Unrecorded
R32E, W.M., Umatilla County, Oregon.						Surveyed in
22 (12)					X	_Referenced out
Drawieure	Demesurale / C					

Previous Renewals / Surveys, etc.

This corner was originally set by Daniel Chaplin under contract No. 107 dated September 21, 1864. His record reads: Set stone, 22 x 15 x 4, for corner to secs. 4, 5, 8 and 9. L.E. Macomber in the Record of Private Surveys Book 1, Page 439 says: Found original stone.

Monument and Accessories found: (condition and source) None. The point falls in the center of George Canyon Road.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

At the intersection of the North - South centerline of the County Road and a fence running East I set a 2 1/2" brass cap on a 1 1/2" x 30" galvanized iron pipe. The cap is 6" below the surface of the road.

For references, I set four, 5/8" by 24" iron rebars with 1 1/4" orange plastic caps stamped WTS and 56295LS as described below:

an iron rebar bears N49°47'52"W, 42.13 feet 20 inches below the surface of a plowed field; an iron rebar bears N32°47'18"E, 61.66 feet;

an iron rebar bears S48°59'46"E, 41.93 feet;

Rec'd By: KF

No. 10-93-C

an iron rebar bears S50°38'09"W, 39.83 feet 20 inches below the surface of a plowed field;

The monument and references were tied using a Trimble R7/R8 RTK GPS System.

Party Chief

Stephen K, Haddock

Location and commentsCompass DeclinationNAD 83/1991 State Plane CoordinateOregon North ZoneN = 704,715.72 iftE = 8,630,142.96 iftFirm / AgencyWitness Tree SurveyingRECEIVED BY:Umatilla County SurveyorDate: 6-10Pilot Rock, Or. 97868

REGISTERED PROFESSIONAL IAND SURVEYOR Stoph V. Halbock OREGON JULY 9, 2001 STEPHEN K. HADDOCK 56295LS RENEWAL DATE 6-30-11

Surveyors Seal