OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 8/12/96

10

CORNER DESIGNATION: J-13. Southeast corner Section 9, TlN., R32E., W.M.

PREVIOUS RENEWALS/SURVEYS, ETC.: Corner originally established by Daniel Chaplin under Contract No. 107, dated September 21, 1864. Surveyor General records state: Set post for corner to secs. 9, 10, 15 and 16 in mound of earth with charred stake, pits &c as per instructions.

MONUMENT AND ACCESSORIES FOUND: Fence intersection, which agrees with improvements and tie to corner shown on railroad maps.

MONUMENT MARKING DETAIL:

TIN R32E S9 | S10 S16 | S15 1996 ORLS 1106

MONUMENT SET: At position determined by old wood hub at fence corner, set a 2 1/2 in. brass cap on a 1 in. x 30 in. galvanized iron pipe, projecting 2 in. out of the ground. (marked as shown in hew Accessories:

A Pacific Power and Light Pole #099000 bears South 82° East -196.5 feet, to brass washer nailed to pole. A 7 in. x 9 in. railroad tie gate post bears South 41 1/2° West -140.7 feet, to brass washer nailed to pole. A 9 in. diameter pole fence corner post bears South 77 1/2° West -88.3 feet, to brass washer nailed to pole. A 7 in. x 9 in. railroad tie gate post bears North 61 1/4° East -51.7 feet, to brass washer nailed to pole. All new accessories have bearing object signs attached. A survey monument sign is attached to the fence corner post alongside the brass cap monument. Brass washers are stamped "PLS

LOCATION & COMMENTS:

COMPASS DECLINATION: 18° East.

Surveyor's Seal

1

See.

FIRM/AGENCY: William R. Wells, PLS P.O. Box 1696 Pendleton, Oregon 97801

Witness: William L. Hanley, PLS Kelly Snively

REC	GISTERED
PROF	ESSIONAL
LAND	SURVEYOR
Vill	Rule
	REGON Y 22, 19-7
WILLI	AM R. WELLS
	1106

RECEIVED BY Unstille Conty Surveyor 10-96