# **OREGON CORNER RESTORATION FORM**

Section 30 Township 1 N Range 37 E.

County\_Umatilla

Date\_Sept., 1993

### CORNER DESIGNATION

1/4 corner, sections 30/31	Not Found X Renewed
corner index: V-3	Unrecorded
	Surveyed In
	Referenced Out

### Previous Renewals/Surveys, etc.

1882 Herman Gradon, set a basalt stone 18"x7"x5", 12" in the ground, marked with a 1/4 on the north face, from which; 12" pine bears N.35°W., 18.5 feet scribed per manual of instruction. 7" fir bears S.10°E., 14.5 feet scribed per manual of instruction.

# Monument(s) & Accessories Found: (Condition and Source)

At a record topo call distance from the creek (4.5 chains) I found a 21" douglas fir badly decayed with a healed face facing in the proper direction for the original fir which is in the southeast quadrant. I chopped into the face, at the proper 7" diameter, I found a hardened face that was decayed beyond recognition of any scribe marks. There was an axe mark at the lower portion of this face. This position is consistent with the short 1/2 mile distances (2570') that I have retraced between found section corners on the east and west section line.

#### Monument Detail

Sketch



\_ Condition Report Only

# Monument Set (Procedures and Description)

At a record bearing and distance pull from the original southeast bearing tree, I set a 3-1/4" aluminum cap on a 2-1/2"x 30" aluminum pipe, 25" in the ground, with a land survey monument sign attached to a steel post nearby.

#### New Accessories

18" ponderosa pine bears S.82-1/2°W., 27.9 feet scribed 1/4S31BT. 21" ponderosa pine bears S.45°E., 38.9 feet scribed 1/4S31BT. 1-1/2" aluminum cap (PLS 2535) on a 5/8"x 24"rebar bears N.19-1/2°E., 17.7 ft, cap is stamped 17.7 RM with an arrow pointing toward the corner. 1-1/2" aluminum cap (PLS 2535) on a 5/8"x 24"rebar bears N.71°W., 18.4 feet, cap is stamped 18.4 RM with an arrow pointing toward the corner.

I painted a 6" red band around all bearing trees and attached a bearing tree sign on the front with a land survey monument sign on the back. On the new bearing trees I attached a brass washer "PLS 2535" in the BT portion of the blaze.

#### Location & Comments

EEC	JELAN 13	1 15 1	
mault	a Cira	-7	1. 1. 4
ate	12	12	$\leq 4 \mathrm{d} \tau^{-2^{n+1}}$
loc'd I	3y_K	Laser interior	R
No	93-	13	1

Compass Declination 18° east Firm/Agency: White Shield, Inc. Address: P.O. Box 477. Grandview, WA 98930 Party Chief: Dennis Hartmans Notes field bk. 3, pg. 4 Witness<u>Wes Cochran</u>

Surveyor's Seal

	REGISTERED PROFESSIONAL LAND SURVEYOR	]
1	nuland P. F.J	lum
	OREGON 11/2 JAN. 21, 1992 MICHAEL P. LE JEUNE 2535	193

expires Dec. 31 1994