OREGON CORNER RESTORATION Section: 1, 2, 11, 12 Township:		
County: Umatilla Date: 2/14/2		
Corner Designation: 3N33E21		
Section corner common to Sections 1, 2, 11,	12, T3NR33E 	X Condition Report Only Not Found Remonumented Unrecorded Surveyed In X Referenced Out
Previous Renewals / Surveys, etc. Originally surveyed by Chaplin in 1864. He set a post in a mount of earth. In 1976 Krumbein set a brass cap in Survey M-121-C.		
Monuments and Accessories Found: (Condition and Source): A 2 1/2" brass cap, 7" below the road surface. A 2 1/2" brass cap witness corner lies S1° 45' E, 19.50'. A 2 1/2" brass cap witness corner lies N 5° 20' W, 17.65'.		
Diagram		Sketch
T3NR33E	ORANGE MAGNET .	^О вс wc
$ \left(\begin{array}{c c} S2 & S1 \\ S11 & S12 \end{array}\right) $	DEINING RD.	О _{вс}
PLS 933 1976		
NAD 83/91 OREGON STATE PLANE NORTH INTERNATIONAL FEET		
N769104.70 E8676240.08		
Monument(s) Set (Procedures and Description): None.		
References Set: "Deep One" magnet by Berntsen. An orange magnet lies N 68° 45' W, 40.02', A 5/8" x 30" iron rebar w/RPC #43406 lies S		
Location and Comments: The corner is 1/2 mile East of the intersection of the Helix Hwy. and Deining Rd.	<u>Compass Declination</u> 17° E	Surveyors Seal
		REGISTERED PROFESSIONAL LAND SURVEYOR
RECEIVED BY:	Firm / Agency	Boost a zylich OREGON
	Survey One, LLC. P.O. Box 382	JANUARY II, 2005 ROBERT DOUGLAS ENGLISH 43406LS
Date: <u>7//0 (20/2</u> Rec'd By: <u>X. Alex</u> No. <u>72-094</u> -C	P.O. B0x 362 Pendleton, OR 97801 (541) 276-2055	RENEWAL DATE: 12/31/13