| OREGON CORNER LESTORATION FORM COUNTY: Umatilla DATE: October 6, 2005 CORNER DESIGNATION: E-1 Northwest Corner Section 7, T. 4 North, Range 29 E.W.M. PREVIOUS RENEWALS/SURVEYS ETC. William Campbell set a post in mound of earth with trench and pits (Contract No. 95, dated September 19, 1860). In 1980, Krumbein set a brass cap in his remonumentation survey for Umatilla County, Survey No. S-156-C. | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| CORNER DESIGNATION: E-1 Northwest Corner Section 7, T. 4 North, Range 29 E.W.M. PREVIOUS RENEWALS/SURVEYS ETC. William Campbell set a post in mound of earth with trench and pits (Contract No. 95, dated September 19, 1860). In 1980, Krumbein set a brass cap in his remonumentation | |
| PREVIOUS RENEWALS/SURVEYS ETC. William Campbell set a post in mound of earth with trench and pits (Contract No. 95, dated September 19, 1860). In 1980. Krumbein set a brass cap in his remonumentation | |
| William Campbell set a post in mound of earth with trench and pits (Contract No. 95, dated September 19, 1860). In 1980. Krumbein set a brass cap in his remonumentation | |
| In 1980, Krumbein set a brass cap in his remonumentation survey for Umatilla County, Survey No. S-156-C. | |
| | |
| | |
| | |
| | |
| | |
| MONUMENT AND ACCESSORIES FOUND: Found Krumbein's brass cap approximately 1 foot below the gravel intersection of Ott and Hooker Roads. Monument was tied before road reconstruction and is now approximately 16 inches below the pavement of a newly paved intersection. | |
| $ \begin{array}{c ccccccccccccccccccccccccccccccccccc$ | |
| LOCATION AND COMMENTS: MONUMENT SET (PROCEDURES AND DESCRIPTION): Corner is at the intersection | |
| Made GPS tie to corner prior to road construction. Set a 2" aluminum cap on | |
| above 1/2" below the surface of the FIRM/AGENCY: | |
| Umatilla County Road Dept. 3920 Westgate Pendleton, Oregon 97801 | |
| NEW ACCESSORIES: PARTY CHIEF: Gary Roberts None. Accessories shown on restoration NOTES: | |
| form for this corner, Survey No. 03-52-G, are still intact. | |
| SURVEYOR'S SEAL | |
| RECEIVED BY Umatilla County Surveyor Date 10-05 UMAY 30, 0000000000000000000000000000000000 | |
| Rec'd By K No. 05-177-R RENEWS 12/31/06 | |