ORE N PUBLIC LAND CORNER REPORT / RESTORATION RESTORATION REPORT / RESTORATION RESTORATION REPORT / RESTORATION RE

20 20 24 22	TOWNSHIP	RAN		
29,30,31,32	4 North	37 Ea	ast	
COUNTY: Umatilla				DATE
			September 15, 2007	
CORNER DESIGNATION: Section Corner Common to sections 29, 30, 31, 32			(Please check one)	
			X	Condition Report Only
				Not Found
			12	
				Surveyed In Referenced Out
Previous Renewals / Sur	vevs. etc.		10	Referenced Out
Monument(s) & Accessor Railroad spike in road	ries Found: (Condition & Source	ə)		
Monument Detail: Railroad spike in west bo punched in top center of s finish asphalt grade.	und lane of HWY 204. Center spike 1 foot 6 inches below	Sketch:	30	SZ MENANTANO
Monument Set (Procedure	es and Desctiption):			
N				
New Accessories: 6" monument box set flus	h with finish grade of pavement.			
6" monument box set flusi	h with finish grade of pavement.		Co	ompass Declination: 84 57 01 W
6" monument box set flusi	distance and bearing from BT t eys, LTD polphin		S	ompass Declination: 84 57 01 W URVEYOR'S SEAL
3" monument box set flus cocation & Comments: 224 ft BT tag on sign post Firm / Agency B & D Surv 2165 SE D Warrenton Party Chief Darryl Niemi PLS 1106	distance and bearing from BT t eys, LTD polphin		S E	84 57 01 W
" monument box set flus location & Comments: 24 ft BT tag on sign post irm / Agency B & D Surv 2165 SE D Warrenton Party Chief Darryl Niemi PLS 1106	distance and bearing from BT t eys, LTD polphin		S	URVEYOR'S SEAL
3" monument box set flus cocation & Comments: 224 ft BT tag on sign post Firm / Agency B & D Surv 2165 SE D Warrenton Party Chief	distance and bearing from BT t eys, LTD polphin		S	URVEYOR'S SEAL RECISTERED ROFESSIONAL, D SURVEYOR

RENEWARUE 12-31-08

07-273-R