History of original corner establishment:

No corner was originally set.

DIAGRA	AM
T5N	R38E
$N \frac{1}{16}$	- S8

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1"x30" Galvanized Pipe with 3" brass cap stamped:

Set pipe 22" in ground with mound of stone and dirt to cap.

New BTs:

A White Fir 22" dia. bears $S36^{0}E$, 52.3 ft., scribed CN 1/16 S8 BT.

A Spruce 6" dia. bears N85 $^{\rm O}{\rm W},$ 45.7 ft., scribed CN 1/16 S8 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.



 $C_{ROWN}^{ROWN} \xrightarrow{ZELLER_{B}} C_{ROWN}^{ROWN}$ $\frac{15N}{16} \int_{C}^{R38E} S8$ $\frac{1980}{PLS} 1294$

I hereby certify the above corner monument was established as herein described on October 27, 1980.

Witnesses: R. Orton A. Hanley

for second on the day of December 1980 Danie Mumbein by Bothy & Sotty Al (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO---798-276

R-186-B