

Notes for Resetting:

The Northwest corner of Section 12, Township 5 South, Range 32 East, W.M.

I found a stump of a Ponderosa pine that had a BT carved in it. Assuming this stump to be the original 28" pine bearing North 43° East links, I back tracked South 42° West 96 links. This point was in bank of small stream in a meadow or swale composed of alluvial soil.

At this point I started to dig. The soil was very friable and contained no rocks. A few inches under the surface I found a stone with several stones nearby. This stone fit the description of the stone placed there by the original surveyor; this stone was sitting in a position in which surveyors customarily place them. There were no other stones in the vicinity of this group.

As a further check I measured the called bearings and distances of the original survey. In all cases I found rotted stumps fitting the calls. However I was unable to find markings in the deteriorated wood.

A further check showed old fence lines converging in this direction,

I therefore accepted this stone as being the original corner and placed a $1\frac{1}{2}$ galvanized iron pipe with a brass cap marked:



From this stone witness trees were marked as follows:

A	14"	Ponderosa	Pine	bears
N	170	W - 83.0 1	feet	S. 2 BT
A	14"	Ponderosa	Pine	bears
N	620	E - 107.4	feet	S 1 BT
A	26"	Ponderosa	Pine	bears
S	200	W - 116.0	feet	$_{\rm BT}^{\rm S}$ 11

O. Harris RLS #346

RECEIVED BY Umatilla County Surveyor Date <u>4-81</u> Rec'd By<u>BLS</u> No: <u>S-28-M</u>