## OREGON CORNER RESTORATION FORM

Section:	27		
Township:	6N		
Range:	34 EWM		
County:	Umatilla		
Date:	12/30/99		
Corner Des	ignation: V-13		

Previous Renewals/Surveys, etc.: Original GLO corner established as a post, with pits and mounds, by Odell, under contract No. 110, in 1865.

Monument(s) & Accessories Found (Condition & Source: No evidence found.

Monument Detail: Set 5/8" rebar with 2 1/2" Aluminum cap 14" deep in field.

TOMKINS SURVEYING T6N R34E 28 | 27 + 33 | 34 1999 WA 25893 OR 2360

Monument Set (Procedures & Description):

At a computed double proportioned position using the established corners at the NW corner of S.28, the NE corner of S.26, the West 1/4 corner of S.15, and accepting a fence corner for the SW corner of S.34 (see LCR), we set the corner described above. The corners were tied and set using Trimble 4400 receivers using real time kinematic methods having standard errors of 1cm plus 2ppm times the baseline length.

## New Accessories:

We set:

A 5/8" rebar w/ yellow cap stamped `Tomkins Surveying' which bears N45°W 10.0' from the corner. Bar buried 10" deep.

A 5/8" rebar w/ yellow cap stamped `Tomkins Surveying' which bears N45°E 10.0' from the corner. Bar buried 10" deep.

A 5/8" rebar w/ yellow cap stamped `Tomkins Surveying' which bears S51°E 60.82' from the corner, and attached B.O. tag to fence post.

A 5/8" rebar w/ yellow cap stamped `Tomkins Surveying' which bears S26°w 44.15' from the corner, and attached B.O. tag to fence post. Location & Comments:

The corner falls in field 50' north of the Road, 50' West of a fence comming up from the south on the south side of the road.

## **Compass Declination:**

Surveyor's Seal

19° East Dec. used to tie B.O.'s,

## Firm/Agency:

Tomkins Land Surveying, Inc. 20 E. Poplar Ste. 204 Walla Walla WA 99362

Party Chief:	Thomas	s.	Butler
Notes:	Thomas	s.	Butler
Witness:	Brianna	a S	later



00-31-B.