

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 01/15/2015

CORNER DESIGNATION: L-9, Quarter Corner Section for Sections 17 and 16, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set stone 15 x 17 x 20 with mound and pits for 1/4 Sec. Cor.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

LS 02820
T 6N | R 37E
S 17 | S 16
 1/4
 1/2015

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set 2 1/2" brass cap on a 1 1/2" x 30" galvanized iron pipe 12" above ground surface with a rock mound, at the base around monument with the following accessories:

- A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N. 55° W., 10.00 feet distance.
- A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N. 47° E., 10.00 feet distance.
- A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S. 42° E., 68.00 feet distance.
- A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S. 44° W., 10.00 feet distance.

LOCATION AND COMMENTS:

Quarter corner is on a steep north facing slope. Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:


N = 858407.61
E = 8785448.88

COMPASS DECLINATION: 15° East


SURVEYORS' SEAL:

FIRM: HDJ Design Group
5 N. Colville, Suite 200
Walla Walla WA 99362

WITNESSES: Joseph R Latimer
Cory A. West



Greg E. Flowers



RENEWS 12/31/15

06/29/2015

15-063-B