## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## W-1 History of original corner establishment: DIAGRAM **T5S R32E** Corner position determined by the Bureau of Land Management by survey during 1968-1980, Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, in a mound of stone 2 1/2 foot N 1/16 34 35 base to top, with brass cap marked: From which: N 1/16 A Fir, 15 ins diam. bears N 85 1/2°E 122 lks. dist., mkd. N 1/16 S35 BT. A Fir, 10 ins. diam., bears N85°W 18 lks. dist., mkd. N 1/16 S34 BT. S34 S35 1968

## Description of corner evidence found:

Found an iron pipe, 2 1/2" diam., firmly set as described in the BLM record, with brass cap attached, marked:

From which the original BLM bearing trees: An 18" White Fir, alive and well-healed, bears N85 1/2°E 80.5 feet, And a 10" White Fir, now dead with well-healed blaze bears N85°W 11.9 ft.

U.S. Dept. of Interior Bureau of Land Management N 1/16 S34 + S35 1968

Description of monument and accessories I established to perpetuate the original location of this corner:

We mark a new BT"

A 12" White Fir, scribed "N 1/16 S34 BT" on a double blaze, bears S 79°W 18.2 ft.

Attached brass washer marked "LS 1099" to lower blaze.

Magnetic Compass (20° East Declination) Steel Tape

August 16, 1984

Witnesses:

Gary Langlitz, LS 1099 Ray Crapo Greg Orton



Meren County of ... matillo Office of . . . . . . . . . . . . . . . . . . . y of October 19.54 State of Snews day of. for record on the..... lo. rember ochra Dan V (COUNTY OFFICIAL) DEPUTY

11, 4024

Form R6-7100-57 (9/71)

\$ GPO-798-276

84-142-R