CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner position determined by Bureau of Land Management during survey performed between 1968-1980,

Set an iron post 28 ins. long, 2 1/2 ins. diam., 14 ins in the ground to solid rock, in a mound of stone, 2 1/2 ft. base to top, with brass cap attached, marked:

1968

DIAGRAM **T5S R32E** N 1/16

No suitable trees available within limits.

Description of corner evidence found:

Found a 2 1/2" dia. iron pipe, firmly set in a mound of stone, with brass cap marked as described in the BLM record.

Description of monument and accessories I established to perpetuate the original location of this corner:

We mark new bearing trees as follows:

An 8" Ponderosa Pine, scribed "CN 1/16 S 32 BT" on a double blaze, bears N 4°E 190.3 ft.

And a 12" Ponderosa Pine, scribed "CN 1/16 S 32 BT" on a double blaze bears S 70°E 289.6 ft.

Attached brass washer marked "LS 1099" to lower blaze of new BT's.

Corner is located 18 ft. south of an E-W fence.

Magnetic Compass (20° East Declination) Steel Tape

August 30, 1984

Witnesses:

Gary Langlitz, LS 1099 Ray Crapo Greg Orton

REGISTERED PROFESSIONAL AND SURVEYOR

GON GARY L. LANGLITZ

...... County of tratella ereby certify that the within instrument was filed in this office (DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276

82-140-R