

AGENDA ITEM FOR ADMINISTRATIVE MEETING

() Discussion only
(X) Action

FROM (DEPT/ DIVISION): Public Works
PROGRAM: 45300-602900 Public Works, Equipment/Miscellaneous
SUBJECT: Used Schmidt Snowblower from Oregon State Surplus Property

<p>Background: The public Works Department is requesting permission to purchase a used 1991 Schmidt 4x4 snowblower from Oregon State surplus property. This would be a welcome addition to our snow removal equipment. The price of the snowplow is \$12,500.00 and, in our estimation, well worth the price. We would plan to use this piece of equipment on our foothill and mountain roads in the winter in an effort to maintain a better level of service to the public.</p>	<p><u>ACTION REQUESTED:</u> Authorization to purchase a used Schmidt snowblower for \$12,500.00</p>
--	---

ATTACHMENTS: Photo and description
Date: (6/16/2025) Submitted By: (Tom Fellows)

*****For Internal Use Only*****

Checkoffs:

- () Exec. Asst.
- () Dept. Head (copy)
- () Human Resources (copy)
- () Budget (copy)
- () Fiscal
- () Legal (copy)
- () (Other - List)

To be notified of Meeting:

Needed at Meeting:

PLEASE RETURN THIS FORM AND ATTACHMENTS TO Executive Assistant

Scheduled for meeting on: June 18, 2025

Action taken:

Follow-up:



Go

Search

Login

[previous item](#) | [back to list](#) | [next item](#)

1991 Schmidt Norland Snowblower 4x4 - Sold on Site at ODOT in Bend, OR.

Received

Oregon #: 279011

Service Charge **\$12,500.00**

1991 Schmidt Norland Snowblower 4x4 - Sold on Site at ODOT in Bend, OR.

DETAIL:

Year: 1991
Make: Schmidt
Model: Norland
Engine Make: Cummins
Engine Disp: 19L
Mileage: 11,501
Hours of Operation: 5052
HP: 600
Cylinders: 6
Fuel: Diesel
Transmission: Automatic
Tire Size: 14.0R24
of Axles: 2
Suspension: Spring
Drivetrain: 4x4
Cab Style: 2
Overall Dimensions: 424"L x 107"W x 131"H
GVWR: 49K

ACCESSORIES:

AM/FM Radio and CD Player.

DESCRIPTION:

Starts and runs with a jump. Battery dead. Overall engine condition unknown. No issues listed at turn in. Has scratches, scuffs and dings

throughout consistent with active use. Interior is worn, torn and has stains. Windshield has rock chips. Evidence of rodents in cab. We do not inspect or perform any diagnostics on vehicles or equipment prior to offering items for sale to determine mechanical or operational condition. Tires have greater than 30% tread remaining. Body: Decal/adhesive remnants.

Inventory: 279011

ODOT Asset ID: 91-0736

Inventory Location

Qty on Hand	Warehouse	Location	Qty On Hand
1		HOLD	1
Service Charge	\$12,500.00		

Images

