

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla. DATE: 03/26/20.

CORNER DESIGNATION: C-13, The East One-Quarter corner of Section 4, Township 1 North, Range 31 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC: Corner was originally established by Josiah A. Burnett under Contract No. 92 dated September 12, 1860. Notes state: Set a post for 1/4 Sec. Cor., drove charred stake and raised mound with trench as per instructions.

MONUMENT AND ACCESSORIES FOUND: None. The corner falls in a farmed area that is presently a CRP field. The corner falls about 50' South of an East-West fence line but lines up with the North edge of a farmed field line to the East.

**MONUMENT MARKING DETAIL:**

T1N R31E  
1/4  
S4|S3  
2020  
54657PLS

MONUMENT SET: Reestablished corner position by single proportion measurement between the Northeast and Southeast corners of Section 4. At the reestablished corner position set a 2 1/2" brass cap on 1 1/4 by 30" galvanized iron pipe. Set steel fence post 2' North of corner and attached Witness sign.

**New accessories:**

A 5/8 by 24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 18°46' E, 55.1' in East-West fence line.

A purple Deep-1 magnet bears S 49°03' E, 29.3'.

A blue Deep-1 magnet bears S 42°45' E, 31.8'.

A 5/8 by 24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 24°20' W, 57.4' in East-West fence line.

Wired bearing object signs to the rebar accessories. Buried bearing object signs with the Deep-1 magnets which are buried 18" below ground line.

Bearings to accessories are State Plane Grid bearings.

LOCATION AND COMMENTS: Corner is located in a farmed field, (currently a CRP field), about 50' South of a East-West fence line.

OREGON STATE PLANE COORDINATE, North Zone NAD 83(91), International Feet Units:

N: 706957.78

E: 8603198.49

FIRM: Wells Surveying  
P.O. Box 1696  
Pendleton, OR 97801

Surveyor's Seal

\IN31C-13



RENEWS: 6/30/20

20-043-C