

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla. DATE: 03/27/20.

CORNER DESIGNATION: E-11, The North One-Quarter corner of Section 9, Township 1 North, Range 31 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC: Corner was originally established by Josiah A. Burnett under Contract No. 92 dated September 12, 1860. Notes state: Set a post for 1/4 Sec. Cor., drove charred stake and raised mound with trench as per instructions. Willard Bradley, County Surveyor, reestablished this corner in his April, 1916 Survey No. 411, and set a stone. In Survey No. 411, Bradley also surveyed through the Northeast corner of Section 9 but does not report recovering the Northeast corner of Section 9. Bradley appears to have used a strange method to reestablish the North One-Quarter corner of Section 9. Survey No. 411 record can be found in the Record of Private Survey Books.

MONUMENT AND ACCESSORIES FOUND: Found and accepted a solidly set 28 by 10 by 3" stone set under a North-South fence line, marked "1/4" on South face. I assume this is the Bradley stone, but Bradley's Survey does not report stone dimensions.

MONUMENT MARKING DETAIL:

T1N R31E  
S4  
1/4 -----  
S9  
2020  
54657PLS

MONUMENT SET: I remove the found stone and at it's position set a 2 1/2" brass cap on 1 1/4 by 30" galvanized iron pipe 27" in the ground. Placed corner stone vertically North of the brass cap monument. Wired a Witness sign to a steel post in the existing fence 3 1/2' North of the corner.

New accessories:

A 5/8 by 24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 02°07' W, 46.8'.  
A 5/8 by 24" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 01°33' W, 23.3'.  
A 5/8 by 15" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears S 02°54' E, 16.0'.  
A 5/8 by 15" rebar with blue plastic cap marked "Wells Surveying 54657PLS" bears N 02°17' E, 31.8'.  
Rebars are set in the existing North-South fence. Wired bearing object signs to the rebar accessories. Bearings to accessories are State Plane Grid bearings.

LOCATION AND COMMENTS: Corner is located on flat ground in a North-South fence line.

OREGON STATE PLANE COORDINATE, North Zone NAD 83(91), International Feet Units:

N: 704197.69  
E: 8600652.65

FIRM: Wells Surveying  
P.O. Box 1696  
Pendleton, OR 97801

Surveyor's Seal

\1N31E-11



RENEWS: 6/30/20