OREGON CORNER RESTORATION FORM					
Section	1	Township	<u>1N</u> Range	32E	
County	Umatilla	_ Date:	July 2, 200	9	
Corner De	signation:	1N32C25			x Condition Report Only Not found
East quarter corner of section 1 only, T1N, R32E, W.M., Umatilla County, Oregon					Remonumented Unrecorded
					Surveyed in Referenced out

Previous Renewals / Surveys, etc.

Corner originally set by David P. Thompson under contract No. 106 Dated August 16, 1864. His record reads: Set stone 15x12x10 ins. for 1/4 sec. corner. Zenas Moody, under contract No. 164 dated September 21, 1871 states: Set stone, 17x14x8 for 1/4 sec. cor. James Currin and James Noland under special contract dated May 4, 1887 state: Found pits & mound. Set a basalt stone 14x12x10 ins. and raised earth mound along side. Lincoln Wilkes in his 1917 resurvey states: Set and iron post, 3 ft. long, 1in. diam. for witness cor. to the 1/4 cor. of sec. 1, with brass cap. Brian Siebold, in his 2000 dependent resurvey states: Set a mag nail, 2 1/2" long, flush with the asphalt. He also set a brass capped witness monument N45°E, 31.00 feet from the mag nail.

Monument and Accessories found: (condition and source) I found the mag nail and a 3" brass cap on a 2 1/2" stainless steel post marked as described by Siebold in good condition.



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None.

This certificate is being filed to report the State Plane Coordinates only.

For references:

The monument and witness corner were tied using a Trimble R7/R8 RTK GPS system.

Location and comments Compass Declination NAD 83/1991 State Plane Coordinate Oregon North Zone N=707,781.70 ift E=8,651,170.30 ift

RECEIVED BY: Umatilla County Surveyor Date: 6-10 Rec'd By: KK No. 10-93-C Witness Tree Surveying Address P.O. Box G Pilot Rock, Or. 97868 Party Chief Stephen K, Haddock REGISTERED PROFESSIONAL LAND SURVEYOR Stephen K. Hadbock OREGON JULY 9, 2001 STEPHEN K. HADDOCK S62951.5 RENEWAL DATE 6-30-11

Surveyors Seal