Section County	10 Umatilla	Township Date:	<u>1N</u> Range July 6, 2009	32E	
Corner Designation: 1N32G17				x	Condition Report Only
Quarter corner common to sections 10 and 11,					Remonumented
T1N, R32E, W.M., Umatilla County, Oregon.					Unrecorded
					Surveyed in
					Referenced out

Previous Renewals / Surveys, etc.

Corner originally set by Daniel Chaplin under contract No. 107 Dated September 21, 1864. His record reads: Set post for 1/4 section corner in mound of earth with charred stake, pits, etc., as per instructions. Zenas F. Moody under contract No. 164 dated October 4, 1871 states: Set post. Currin and Noland under special contract dated May 4, 1887 state: Set stone 7 x 8 x 9 ins., 6 ins. in the ground. L.E. Wilkes in 1917 set a brass cap witness corner 1lk south of the true corner. Survey H-250-B states: Found original stone 9x8x7. David H. Krumbein in record of survey 03-232-B states: Found rock. David L. Haddock in record of survey 05-100-B states: Found stone and brass cap witness corner.

Monument and Accessories found: (condition and source) I found the stone by Currin and the brass cap by Wilkes in good condition.



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) I made no modification to the monument or accessories. This purpose of this certificate is to report the state plane coordinates of the corner point. The coordinate given is of the true corner point and not the witness monument by Wilkes.

For references:

This monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments	Compass Declination	Surveyors Seal
NAD 83/1991 State Plane Cool	rdinate	
Oregon North Zone		A
N = 702,291.49 ift		REGISTERED
E = 8,640,700.89 ift	Firm / Agency	PROFESSIONAL
	Witness Tree Surveying	LAND SURVEYOR
RECEIVED BY:	Address	Stephen K. Haldon
Umatilla County Surveyor	P.O. Box G	
Date: 6-10	Pilot Rock, OR 97868	OREGON JULY 9, 2001
Rec'd By:	Party Chief	STEPHEN K. HADDOCK
No. 10-93-C	Stephen K, Haddock	56295LS

RENEWAL DATE 6-30-11