OREGON CORNER RESTORATION FORM					
Section County	14 Umatilla	Township Date:	<u>1N</u> Range February 27, 2009	32E	_
Corner De	signation:	1N32L21			Condition Report Only Not found
Quarter corner common to sections 13 and 14, T1N, R32E, W.M., Umatilla County, Oregon.				X	Remonumented Unrecorded Surveyed in
Previous F	Renewals / Su	irveys, etc.		X	_Referenced out

Corner originally set by Daniel Chaplin under contract No. 107 Dated September 21, 1864. His record reads: Set stone, 18 x 8 x 6, for 1/4 sec. cor. Zenas F. Moody under contract No. 164, dated October 4, 1871, stated: Set post. Currin and Noland under special contract dated May 4, 1887, stated: Set stone 18 x 10 x 8 ins. In record of survey H-255-B, found original stone 18 x 10 x 2 and set reference monument. In survey Q-57-Ax, Ralph Thompson states: found stone 8"x12"x18", 6 feet below the surface. Raised stone and reset.

Monument and Accessories found: ( condition and source )

I found a 1" iron shaft witness monument 30 feet west in the fence. I found a basalt stone 18x9x6 ins. marked 1/4 on the west face 10 inches below the surface of the road with a decayed 2" wooden survey hub over the top of the stone.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) Set a 1 1/2" x 30" galvanized iron pipe with a 2 1/2" brass cap stamped as shown in the diagram above at the position of the original stone.

For references, I set two 5/8" by 24" iron rebars with 1 1/4" orange plastic caps stamped WTS and 56295LS as described below:

an iron rebar bears S20°12'46"W, 65.17 feet 2 feet below the surface;

an iron rebar bears S23°16'33"E, 66.77 feet 2 feet below the surface;

the Refuge Survey witness monument (1" iron shaft) bears S89°54'59"W, 29.31 feet under the existing fence.

**Compass Declination** 

A 3" brass cap (Refuge monument No. 12) bears N04°27'05"W, 380.24 feet;

The monument and references were tied using a Trimble R7/R8 RTK GPS system.

Location and comments NAD 83/1991 State Plane Coordinate Oregon North Zone N = 697,103.57 ift E = 8,646,062.48 ift

RECEIVED BY: Umatilla County Surveyor Date: 6-10 Rec'd By: KK No. 10-67-0Firm / Agency Witness Tree Surveying Address P.O. Box G Pilot Rock, OR 97868 Party Chief Stephen K, Haddock

REGISTERED PROFESSIONAL LAND SURVEYOR Hallock OREGON JULY 9, 2001 STEPHEN K. HADDOCK 56295LS RENEWAL DATE 6-30-11

Surveyors Seal