OREGON CORNER RESTORATION FORM

Section 30 Township 1 N Range 37 E.

County Umatilla Date

illa ____ Date_Sept., 1993

CORNER DESIGNATION

	Not Found
	X Renewed
1/4 corner between 25/30 index code: T-1	Unrecorded
	Surveyed In
	Referenced Out

Previous Renewals/Surveys, etc.

1881, Jacob C. Cooper, established a corner tree, a 3" thorn tree marked 1/4S on the east and west faces, from which;

28" balm bears S.80°W., 9.9 feet scribed per manual of instruction. no other trees within limits, raised a mound of stone alongside.

1989, Duane Griffith, PLS 644, set this 1/4 corner by single proportion.

Monument(s) & Accessories Found: (Condition and Source)

I found a 3-1/4" aluminum cap monument firmly set in a rock cairn, from which;

33" white fir bears N.45°E., 82.45 feet with scribing visible.
28" ponderosa pine bears S.29°W., 56.62 feet with scribing visible.

Monument Detail

Sketch



_ Condition Report Only

Monument Set (Procedures and Description)

New Accessories

From the existing monument I established the following;

1-1/2" aluminum cap (PLS 2535) on a 5/8"x 24"rebar bears S.21°E., 12.3 feet, cap is stamped 12.3 RM with an arrow pointing toward the corner. 1-1/2" aluminum cap (PLS 2535) on a 5/8"x 24"rebar bears N.83-1/2°W., 9.4 feet, cap is stamped 9.4 RM with an arrow pointing toward the corner.

Location & Comments

				- 22
	30 10	Ten 1		
Urnal	1219 .011	क्षारतंत्र	Serious	and he
Deda	Ia	-9	13	. will
Ruo'd	in fation	VE	Le consen	V-1185-Q
No C	72-	93	R	na desista

		ination White		
		O. Box		
		A 9893		
Party	Chief:	Dennis	Hartm	ans
Notes	Field	bk. 3,	pg. 1	9
		Cochran		

Surveyor's Seal

DI	REGISTE		
	ROFESS		
m	but	P.3	Jean
MIC	OREGO JAN. 21, 19 HAEL P. LE	N 11/4	793
MIC	2535		