USDA-FOREST SERVICE Index File No. X-27-25	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No
T 1N R. 528 36E	R.D. WALLA WALLA County UMATILLA
Merid. <u>WILLAMETTE</u>	N.F. <u>UMATILLA</u> State <u>OREGON</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
S 31	Found no evidence of the original corner monument.
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	Found no evidence of the original corner accessories.
PHOTO IDENTIFICATION DATA 12 616140A 787-58 Photo No.	
Filed At. Ranger Office	
Object Iden Bearing Trees	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident By D. I. Griffith	Corner falls on a very steen Fact fore
Signature 7	Corner falls on a very steep East face approximately 600 feet North of the end of a skid trail and approximately 250 feet North of a draw.
PLANE COORDINATE POSITION DATA	end of a skid trail and approximately
State Zone	200 leet worth of a draw.
x	
Υ	
Estab. By	··
Aginey 8	4
was Signative	Title Division Headquarters Date FS-7100-52 (3/68) Surveyor 9-19-89

USDA-FOREST SERVICE	
Index File No. X - 25	CORNER RECORD (SEARCH) Tractor Cor.
	(Def Eth 71e) A CAi
Merid. WILL	R.D. WALLA County LINATILLA
CORNER DIAGRAM	N.F. LLMATILLA State DREGON
TIN	DESCRIBE CORNER MONUMENT FOUND
1 R36E 14 R37E	None
N S 36 0 S 31	
1 '	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
'	NONE - FOUND A TREE (FIR) WITH A
	1 TAURE (FIR) WITH H
e	VERY OLD BLAZE JUST NORTH
PHOTO IDENTIFICATION DATA	OF SEARCH AREA.
Photo No.	
Filed At.	
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	TO NEAR-DI FEATORES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA	
State Zone	
×	
Estate. By	
Agency 8	
Signature 2	Division Headquarters Date ES 7100 EQ (2/68)
Jennis & X/ay	loid L5 1636 5,0, 6-88 FS-7100-52 (3/68)

CODNED	DECADA	/ DEDDETHATION \
CORNER	RECURD	(PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Index File No.

Τ.

R.

ACCESSORIES DESCRIBE NEW 8T'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By Title	Date	State Registration No. or Agency	_
Certified Cor. Record Prepared ? Yes No	Filed At:	Date	1

REMARKS

GPO: 1984 O - 439-095

Cor.

Tract or Surv. No.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½"x30" aluminum pipe with aluminum cap marked as shown: Pipe is set 20 inches in the ground.

T1N R36E ₁ R37E

Raised a mound of stone around monument, 3 ft. base to top of cap. S 36 S 31 1989 OPLS 644

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New Bearing Trees:

A 28 inch diameter Douglas Fir bears S25°E, 89.6 feet marked ¼ S31 BT A 20 inch diameter Douglas Fir bears S68°W, 46.0 feet marked ¼ S36 BT.

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fence post approximately 5 feet North with 54-9 and 54-2 signs attached.

Work Done By D. I. Griffith

Title Surveyor

Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Surveyor's Office Date 9-89

REMARKS

Witnesses: Jeff Petersen and Rick Robinson

Index File No. X OF T. 1N R. 37E W.M.
25 36E GPO: 1986 0 - 439 - 09

.M. Tract or Surv. No. GPO: 1986 0 - 439-095

Cor.

13