	·····	······································						
Section: 1	CORNER R 10, 11 Umatilla	ESTORATION Township: Date: 5/25/2	3N	Range:	33E			
Corner Desig	<b>jnation</b> : 3	N33G17						
Previous Ren	newals / Surve	Sections 10, 11, Ta <b>ays, etc.</b> I <sup>j</sup> in in 1864. He se		mound of ea	erth.	X X X X	Condition Rep Not Found Remonumente Unrecorded Surveyed In Referenced O	ed
<u>Monuments a</u> None.	Ind Accessor	ies Found: (Cond	lition and S	ource):				
Diagra		Sketch						
T3NR3 1/4 S10 •				ORANGE MAGNET		5	SILVER 1AGNET	
PLS434( 201			FIELD LI	FIELD LINE				
NAD 83/91 OREGON STA INTERNATION N766310.33 E8671021.69		ORTH		BLUE MAGNE	T		PINK MAGNET	
A 1 1/8" x 30" g	galvanized iror ation was rees	res and Descripti 1 pipe with a 2 1/2 tablished by a con	" brass cap.	stamped as single propo	shown a rtionate r	bove, 1.4' bone to the bone to	elow the surfac holding a long	е.
A silver magnet	agnets by Berr Inet lies N 43° t lies N 26° E, lies S 49° E, 1	ntsen. 15' W, 22.70', 1.3 22.17', 1.2' deep. 7.73', 1.4' deep. 20.00, 1.3' deep.	' deep.					
Location and C The corner is lo 1/2 mile West o Rd. and the Hel	cated 1/2 mile f the intersecti	South and	ompass Dec 17° E	lination		REGIS	ors Seal STERED SSIONAL URVEYOR	)
RECEIVED	BY: 2/10/20, 2-09-1-	12 2 C	Firm / Ag Survey O P.O. Box Pendletor (541) 276	ne, LLC. 382 1, OR 97801		JANUAR OBERT DOUG 434	Eylyd 200N Y 11, 2005 GLAS ENGLISH 06LS ATE: 12/31/13	]