CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established by Saxton in 1909. Harris found 1 1/2 inch iron pipe in 1976. Krumbein set 2 1/2 inch brass cap in 1980. Roberts referenced brass cap in 1995.

Description of corner evidence found:

Found 2 1/2 inch brass cap buried 12 inches below the road surface of the North travel lane of West Punkin Center Road, at its intersection with N.W. Geer Road; mkd: as shown.

From which I find the stated references intact and undisturbed:

- (RM 1) A 5/8 inch iron rebar with yellow plastic cap mkd: UMA CO R D LS 2627, bears N33°57'E, 38.53 feet dist.
- (RM 2) A 5/8 inch iron rebar with yellow plastic cap mkd: UMA CO R D LS 2627, bears S45°09'E, 36.27 feet dist.
- (RM 3) A 5/8 inch iron rebar with yellow plastic cap mkd: UMA CO R D LS 2627, bears S50°14'W, 48.55 feet dist.
- (RM 4) A 5/8 inch iron rebar with yellow plastic cap mkd: UMA CO R D LS 2627, bears N43°34'W, 43.63 feet dist.

Description of monument and accessories I established to perpetuate original location of this corner:

At surface of asphalt, I set a 2 inch MAG nail with 1 1/2 inch stainless steel washer mkd: WA LS 2872, directly over the brass cap.

NAD 83 Geodetic Position Lat. 45°51'52.9" N Long. 119°18'01.6" W

Established by: Trimble RTK

I hereby certify that the corner is monumented and accessories taken as described, using dual frequency carrier-phase GNSS receivers.

Witnesses: Kristina Powell and David Quittschreiber





	REGISTERED PROFESSIONAL
	LAND SURVEYOR
1	Codnar Lawis
	<u> </u>
	OREGON JULY 21, 1998
	OREGON

Office of	County Surveyor		Cou	ntv of	Umatilla			
				-		filed in this office		
for record on the	ə c	day of		, 2017				
by								

(COUNTY OFFICIAL)

(DEPUTY)

17-059-B

☆GPO — 798-276