OREGON CORNER RESTORATION FORM


SECTION 6 TOWNSHIP 4N	RANG	E 28E CORNER	LOCATION COD	EE-5	_
100020077		MARCII			
COUNTY: UMATILLA	_DATE:_	1994			
CORNER DESIGNATION SE CORNER OF SECTION	6. T4N.	R28EW.M	CONDITIONNOT FOUNDRENEWEDUNRECORDEISURVEYED _X REFERENCEI) IN	ONLY

PREVIOUS RENEWALS/SURVEYS, ETC.

ORIGINAL SURVEY BY HAFT IN 1860. CONTRACT NO. 93. 1° IRON BAR SET BY STAEBLER IN 1974 IN PLACE OF FOUND IRON SPIKE. THIS SURVEY COUNTY NO. 94-022-C. EDWARDS FOR OREGON DOT..

MONUMENTS & ACCESSORIES FOUND: Condition and Source

FOUND IN GOOD CONDITION A I' IRON BAR O.I' BELOW SURFACE OF ASPHALT.



MONUMENT SET (Procedures and Description) DID NOT SET NEW MONUMENT.

NEW ACCESSORIES

ALUM. TAG #951 IN POWER POLE BEARS N 37'27'26'E 27.73 FEET.
ALUM. TAG #951 IN POWER POLE BEARS S 15'14'34'E 77.90 FEET.
ALUM. TAG #951 IN POWER POLE BEARS S 14'24'36'W 77.18 FEET.
ALUM. TAG #951 IN R/R TIE BEARS S 88'31'46'W 16.13 FEET.

LOCATION & COMMENTS

FROM THE INTERSECTION
OF BRIDGE ROAD AND
AGNEW ROAD, GO NORTH
ALONG AGNEW ROAD I MILE
TO CORNER.

RECEIVED BY

Useatille County Surveyor

OREGON JULY 18, 1971 G. DENNIS EDWARDS

RENEWS 12/31/95

SURVEYOR'S SEAL

REGISTERED PRCFESSIONAL LAND SURVEYOR