OREGON CORNER RESTORATION FORM

Section: Corner common to sections 14, 13, 24 & 23 Township: 4N Range: 37 EWM County: Umatilla Date: 12/01/99 Corner Designation: N-19 N-2.1

Previous Renewals/Surveys, etc.: This corner was originally set by U.S. Deputy surveyors, Charles L. and William C. Campbell, under Contract No. 733. Dated March 22, 1901. The Surveyor Generals notes state: "Set a pine post, 4 ft. long, 6 ins. Square, 24 ins. In the ground, struck rock and raised a mound of stone around for Cor. of Secs. 13, 14, 23 & 24, marked T4N S13 on N.E., R37E S24 on S.E., S23 on S.W. and S14 on N.W. faces, with 3 notches on S. and 1 notch on E. edges, from which: A pine, 16 ins. Dia. Brs. N.40°W. 2.97 chs. Dist, marked T4N R37E S14 BT. Raised a mound of stone 2 ft. base, 1 ½ ft. high W. of cor., pits impracticable.

Monument(s) & Accessories Found (Condition & Source): Found the remains of a mound of stone 4 feet in diameter on a steep Westerly slope 25 feet South of the crest of a narrow ridge. A 27 inch down pine snag with visible scribing bears N41 ½ ° W 167.3 feet to the stump hole.

Monument Detail: TOMKINS SURVEYING

T4N R37E S14 S13 S23 S24 1999 WA 25893 OR 2360

Monument Set (Procedures & Description): At the location of the found mound of stone set a 5/8" x 30" iron rebar with a 2" aluminum cap marked as noted, 4" in the ground, struck rock. Erected a stone mound 4' in diameter 2' high around the monument.

New Accessories: A steel fence post with a land survey monument sign was placed 4' North of the corner.

A 15" Douglas fir bears N52°E 94.1 feet, marked T4N R37E S13 BT

Compass Declination

A 18" ponderosa pine bears S88 1/2 °E 103.2 feet, marked T4N R37E S24 BT

A rock outcropping 3' high marked with an "X" 1 foot above ground bears S28 1/2 ° E 101.0 feet.

A 12" ponderosa pine bears N30 1/2 °W 125.2 feet, marked T4N R37E S14 BT

All bearing trees have a 6" red band painted around them and a Umatilla County Bearing Object sign attached, the "X" BO is painted red and has a Umatilla County Bearing Object sign attached.

Surveyor's Seal

Location & Comments: The corner falls on a steep narrow East West ridge East of Elbow Creek.

19° Ea	ist	⁸⁰ 14	Sur reyor a bear	
Firm/Agency	Tomkins Land Surveying 20 E. Poplar, Suite 204 Walla Walla WA 99362	(A) (A)	REGISTERED PROFESSIONAL LAND SURVEYOR	
Party Chief: Notes:	Greg E. Flowers Greg E. Flowers	EECHIVLD BY	Ang E. Flowe UNE 30, 1997 GREG E. FLOWERS CREG E. FLOWERS	us
Witness:	Bryan A. Martin	Unatilla County Sur Data <u>3-2000</u> Best d By <u>KK</u> No. 00-39-K		