ERTIFIED	RECORD	OF	LAND	CORNER	MONUMENTATION
----------	--------	----	------	--------	---------------

Corner Code No. X-9 Note: Monument marked as shown below
DIAGRAM
T4N R37E
1/4 \$32 i \$33
1991 PLS 1106

Corper No. Compass Declination: 18.0°

Description of corner evidence found:

None. The corner area was thoroughly searched for approximately 3 hours. All evidence of the original corner and it's accessories has been erased by time and logging.

Description of monument and accessories I established to perpetuate the original location of this corner:

This corner was re-established by single proportion measurement between the recovered Southeast corner of Section 32 and the N 1/16th corner common to Sections 32 and 33, established by Douglas M. Ferguson as reported in Survey No. P-113-B.

At the re-established corner position I set a 2 1/2" brass cap on 1 1/4" by 30" galvanized iron pipe, 24" in the ground and surrounded with a mound of earth.

From the re-established corner monument:

A 11" alpine fir bears S 58°W 12.3' scribed 1/4 S32 BT. A 11" western larch bears S 20°E 23.3' scribed 1/4 S33 BT. A 6" western larch bears N 59 1/2°E 21.3' scribed 1/4 S33 BT. A 14" white fir bears N 14°W 17.5' scribed 1/4 S32 BT.

Placed bearing object signs on all new bearing trees.

Set steel fence post North of corner and attached witness corner sign.

	REGISTERED PROFESSIONAL LAND SURVEYOR
	Will: R. Wel
	OREGON JULY 22, 19/7 WILLIAM R. WELLS 1106
Office of	County of
State of	
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)
6 7100 67 (0/71)	RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor Date 9-9 Rec'd By___ No. 9 10

\$ GPO-798-276