CERTIFIED RECOR	D OF LAND	CORNER MONUMENTATION

T 4N, R 37E., W.M.

History of original corner establishment:

This corner was originally established by George S. Pershin, U.S. Deputy Surveyor, under Contract No. 304, dated September 19, 1878.

The original notes state:

Set spruce post on nearly level for 1/4 section corner from which:

A fir 12 in. dia. bears N 38°M, 30 links. A fir 14 in. dia. bears S 30°M, 54 links.

In 1976, under Survey No. L-56-B, original syldence of the corper was recovered and the corner was remonumented with a 2 1/2" brass cap on a 2" by 30" iron pipe.

Cor	ner	Code	No.	Z-19
Note:	Monument	. narked	as shown	below

DIAGRAM	
T4N R37E	
1/4 535	
T3N R37E	
RPE 2808	
1976	

Corper No. Compass Declination: 18.0°

Description of corner evidence found:

Found a 2 1/2" brass cap on a 2 1/2" galvanized iron pipe protruding 4" out of mound of stone. Corner located in North-South fence line about 10' North of fence corner with fences North and East from which:

Rotted remains of a 24" white fir bears S 30° W, 35.6' with parts of a chopped face remaining. (original bearing tree) A 16" white fir bears S 06° E, 20.2' with scribes visible on a partly healed blaze. (RPE 2808 bearing tree). A 12" white fir bears N 56'E, 21.7' with scribes visible on a partly healed blaze. (RPE 2808 bearing tree).

There is a steel fence post with an attention (54-4) sign attached, West of corner

Description of monument and accessories I established to perpetuate the original location of this corner:

Rebuilt earth and stone mound around corner monument.

Marked 2 new bearing trees:

A 10" white fir bears N 88°E, 10.6', scribed 1/4 S35 BT. A 17" white fir bears S 17 1/2°W, 28.9', scribed 1/4 S2 BT.

All bearing trees have U.S.F.S. bearing tree tags or County bearing object signs attached.

	PROFE	SSIONAL SURVEYOR
	OR JULY WILLIAM	• R. Wells
Office of	County of	
for record on the day of		
	(DEPUTY)	
Form R6-7100-57 (9/71)	RECEIVED BY	\$ GPO798-276

Date____ Rec'd By No. 9/

Umatilla County Surveyor