## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by George S. Pershin under G.L.O. contract number 304 dated Sept., 19, 1878.

Surveyor General's records state:

Set a fir post on level for 1/4 sec cor from which:

A fir 24" diam. bears N 54° E., 115 lks dist marked 1/4 S BT A spruce 8" diam. bears S 15° W., 42 lks dist marked 1/4 S BT

		RAA N	R	37 36	
TR	P	N E 197	2 8	1 37. 8 0	E 8

2-23

Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the original location of this corner

Set a brass cap  $2\frac{1}{2}$ " dia. on a 2" iron pipe 31" long 6" above the ground with a 6' steel fence post alongside with a sign 54-4 attached.

new bearing trees:

A fir 10" diam bears N 85°30' W., 84.0 ft dist marked 1/4 S BT A spruce 8" diam bears S 09°30' E., 72.0 ft dist marked 1/4 S ET

Each BT has a sign 54-3 attached 6" below a band of red paint and has a brass washer marked RFE 2808 nailed flush with BT blaze.



- Oregon	crowy of	***************************************
State of	hereby certify that the within	instrument was filed in this office
for record on the . 26. day of	August. 1976	
	and an	

Countr of Umatilla

COUNTY OFFICIAL

Office of Surveyor

(DEPUTY)