	LAND CORNER MONUMENTATION
T 4N , R 37E., W.M.	Corner Code No. Z-3 Note: Monument marked as shown below
History of original corner establishment:	DIAGRAM
This corner was originally established by W.H. Odell, U.S. Deput under Contract No. 114, dated July 2, 1866.	
The original notes state:	1/4 531
Set post corner for 1/4 section from which:	*** S6
A larch 12 in diameter bears N 35° E 12 links. A larch 6 in diameter bears S 09 W 32 links.	T3N R37E
	1991
In 1974, under Survey No. I-153-C, a 2° by 18° pipe was reported re-established corner position.	ly set at the PLS 1106
	Corper No. Compass Declination: 18.0°
Description of corner evidence found:	
Found badly disturbed 2 1/2" O.D. pipe. disturbed by a large uprooted fir.	This pipe was
This position of the 2 1/2" O.D. pipe w 6.46' from position based on single pro	as rejected because it is S 01°15'W, portion measurement.
Description of monument and accessories I establishe	d to perpetuate the
original location of this corner:	
Re-established corner position by singl Southwest corner of Section 31 and the a 2 1/2" brass cap on a 1 1/4" by 30" g surrounded with a mound of earth. Buri sluff dirt.	e proportion measurement between the Southeast corner of Section 32 and set alvanized iron pipe 42" in ground and ed monument deep to get below uproot
From the new monument:	
A 17" white fir with a partly healed bl	aze, bears S 43°W, 31.0'. (Survey
I-153-C). A 16" white fir with a partly healed bl. I-153-C).	
Marked 2 new bearing trees:	
A 9" Englemann spruce bears N 35°E, 5.9 A 6" Englemann spruce bears N 47°W, 11.5	
Placed bearing object signs on all bear:	
Set steel fence post 3.1' West of corner There is an East-West fence line 8' to 4	
	REGISTERED PROFESSIONAL LAND SURVEYOR
	Will: R. Wels OREGON JULY 22, 19/7
	WILLIAM R. WELLS
Office of C State of	ounty of
for record on the day of	, 19
(COUNTY OFFICIAL)	(DEPUTY)
Form R6-7100-57 (9/71)	RECEIVED BY
32990 B2	Umatilla County Surveyor
	Date 9-9/
	Rec'd By
	No. 91-75 .C
	map from fail and and and