## History of original corner establishment:

Corner established in 1882 by George S. Pershin under General Land Office Contract No. 430. Surveyor General's notes states: Set basalt stone 12 x 10 x 8 ins., 8 ins. in 1/4 $\frac{5}{5}$ 12	E
occ budgie acone is A to A o that o that th	
ground on level bench for 1/4 Sec. Cor. 1981 marked 1/4 on N side. PLS 848	
A pine 36 ins. dia. brs. N10°E 58 lks. dist. marked 1/4 S BT. A pine 34 ins. dia. brs. 568°E 22 lks dist. marked 1/4 S BT.	

## Description of corner evidence found:

Searched for corner near midpoint between Sec. Cor. No evidence found. N-S fence runs through position of corner stone has probably been moved into a fence jack.

No bearing tree evidence found; an old fire has destroyed any traces, therefore, the position of the corner is determined by proportion.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown in the diagram, set 16 inches in the ground and raised a mound of stone and earth around the pipe. From which:

A pine 15 in. dia. bears S13°E, 91.5 ft. scribed 1/4 S 12 BT. A pine 11 in. dia. bears N25°E, 2.8 ft. scribed 1/4 S 1 BT. Set steel post with warning sign, N15°W, 5 ft. from corner. N-5 fence, 2 ft. East from corner. Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted red band around each tree.

I hereby certify that the above corner monument was reestablished as herein described on 8/14/81.



Witnesses: Mitchell Ferguson D.

Mike Woodward

Office of Co. Surveyor County of Umatilla State of Dregon , I hereby certify that the within instrument was filed in this office for record on the 72 day of January 1982 Damed Krumber by Betty Shatto (COUNTY OFFICIAL) (DEPUTY)

82-01-C

Form R6-7100-57 (9/71)

\$ GPO-798-276

T-2

4.5

DIAGRAM