USDA-FOREST SERVICE		7.0
Index # - 21	CORNER RECORD (SEARCH) Tract or Survey No	Cor. No.
T <u>45</u> R. <u>30E</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>	
Merid. Willamette	N.F. Umatilla Stote Dregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
T45 R30E S 1/16	Corner not previously established.	
S 11 S 12 1981	DESCRIPE READING TOSSE OR OTHER DESCRIPTIONS	2
PLS 848	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
PHOTO IDENTIFICATION DATA Photo No.		
Filed At.		
Object Ident. Ident. By Signature 7	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HO From the corner Sec. 11, 12, 13 and 14,	which is a
PLANE COORDINATE POSITION DATA State Zone X Y	BLM brass cap with steel posts set N-S- set on East edge of primitive road, go to corner. Corner is near the top of a on slight South slope.	E-W North 1/4 mi
Estab. By	Title Division Headquarters Detail	
Land French	Dota	7100-52 (3, 68)
	PLS 848 Mt. V _e rnon, DR 8/4/8	T 2

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 12 inches in the ground and raised a mound of stone and earth around the pipe.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No bearing trees are available. Set steel posts with warning and boundary signs

5 ft. South and 5 ft. East from corner.

Index File No.

						10
Work Done By D.M. Fergus	<u>500</u> _Title_	Surveyor	8/4/81	State Registration No.	OR PLS 848	
CertifieREGIGTEREDpored 7	Yes XX No	Filed An Umati	lla Co. Su	rv. Office.Date	10/81	- 11
PROFESSIONAL		REMARKS	-			
LAND SURVEYOR						
buttett to				ell Ferguson		
OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848			Mike Woo	dward		

Tract or Surv. No.

Cor.