USDA-FOREST SERVICE GPO 940 Index File No. H - 23 T 45 R. 30E Merid. Willamette	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. No. R.D. Ukiah Umatilla N.F. Umatilla State Dregon	f4 - -
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	=-
T45 R30E C S 1/16; 5 12 C	Corner not previously established.	
Ï 1981	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
PLS 848	N/A	•
6		
PHOTO IDENTIFICATION DATA		
Photo No Filed At	•	
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER	<u>3</u>
Signature 7 PLANE COORDINATE POSITION DATA	Corner on flat open ground. A primitive road	
State Zone	coursing N.E. approx. 300 ft. West from corner. Corner can be seen from that road.	
×	John Bride Toda.	
Y		
Estab. By	The second secon	4
Signature Signature	Title Division Headquarters Date 7100-52 (3.6è) ——PLS 848 Mt. Vernon, DR 8/5/81	<u></u>

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram; set 20 inches in ground and placed a circle of stone and earth around pipe.

From which:

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE A pine 14 inches dia. bears N63°E, 85.8 ft. scribed C5 1/16 5 12 BT. Set steel posts with warning and boundary signs 5 ft. East and 5 ft. West from corner.

Nailed bearing tree signs and brass washer stamped PLS 848 to tree. Painted red band around tree.

No other tree available.

								10
Work Done By. D.M. Ferguson Title	Surveyor	8/5/8		istration No.	OR	PLS	848	
Certified CoFAGLOT FREDRED ? YS X No	Filed At: Umati	lla Co.	Surveyor	Off Date				
LAND SURVEYOR	REMARK	S						<u> </u>
	Ы	itnesses	to above	corner				
Louis WI fee		D	Mitchell	Enna				

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

D. Mitchell Ferguson Mike Woodward

Index File No.

M.

Tract or Surv. No.

Cor.

13