History of original corner establishment:

Corner not previously established.

| DIAGRA | | _ |
|--------|--------|----|
| T Z | 45 R30 | JE |
| | 5 12 | |
| E 1/16 | 5 13 | |
| | 1981 | |
| F | LS 848 | 3 |

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram. Set pipe 26 inches in the ground.

From which: A fir 18 inches dia. bears N54°E, 30.0 ft. scribed E 1/16 S 12 BT. A fir 9 inches dia. bears S56°W, 4.5 ft. scribed E 1/16 S 13 BT. Set steel posts with warning and boundary signs 5 ft. North and 5 ft. South from corner Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.

I Hereby certify that the above corner monument was established as herein described on 8/5/81.

| | Witnesses: |
|--|----------------------|
| REGISTERED PROFESSIONAL LAND SURVEYOR | D. Mitchell Ferguson |
| Van Man | Mike Woodward |
| OREGON JULY 12. 1968 DOUGLAS M. FERGUSON 848 | 2 ¹⁰ |
| Office of .C.o. SURVEY.Dr. County State of Dregon , I hereby certify that the w | orLumatilla |
| for pecord on the. 2th day of and and any | 19.82 |

Form R6-7100-57 (9/71)

\$ GPO-798-276

82-01-C

T-2