CERTIFIED RECORD OF LAND CORNER MONUMENTATION

. . . .

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as sbwn on the diagram, set 24 inches in the ground.

From which:

N/A

A pine 16 in. dia. bears N71°W, 29.5 ft. scribed CN 1/16 S 14 BT. A pine 14 in. dia. bears S19°E,69.3 ft. scribed CN 1/16 S 14 BT. Set steel post with warning and boundary signs 5 ft. West and 4 ft. East from corner. Nailed bearing tree signs and brass washers stampedPPLs 848 toto each tree. Painted red band around each tree.

I hereby certify that the above corner monument was established as described herein on 7/31/81.

Witnesses: D. Mitchell Ferguson

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848

Mike Woodward

Office of CO. Surveyor	County of Umatilla
State ofOregon	fy that the within instrument was filed in this office
for second on the ? the day of Januar	y
Navid nrumber	by Billy Thatto
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276

82.01-C

T-2