History of original corner establishment:

Corner not previously established.

DIAGRAM	
T45	R30E
E J	/16
C	·C
S	13
19	981
PLS	6 848

1-24

Description of corner evidence found: N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram. Set 16 inches in the ground and raised a mound of stone around the pipe. From which: A pine 10 inches dia. bears N41°E, 38.5 ft. scribed CE 1/16 S 13 BT. A pine 9 inches dia. bears S57°E, 55.8 ft. scribed CE 1/16 S 13 BT. Set steel posts with warning and boundary signs 5 ft. South and 5 ft. West from corner. Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted a red band around each tree.

I hereby certify that the above monument was established as herein described on 8/6/81.

[	REGISTERED PROFESSIONAL	]
ſ	OREGON JULY 12, 1988 DOUGLAS M. FERGUSON	1

Witnesses: D. Mitchell Ferguson

Mike Woodward

Office of Co. Surveyor	County of Umatilla
State of Oregon	y that the within instrument was filed in this office
for record on the day of aninans	1
(COUNTY OFFICIAL)	that the within instrument was filed in this office 

Form R6-7100-57 (9/71)

\$ GPO---798-276

82-01-0

T-2