History of original corner establishment:

Corner not previously established.

	DIAGRAM	
	T4S R30E	
E	$5 \frac{14}{1/16 - \cdot - \frac{5}{5} 23}$	
	1981	
	PLS 848	

1

 $\mathbf{x}_{\mathbf{a}}$

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner: Set 3"x30" galv.iron pipe with 3" brass cap, stamped as sho diagram, set 16" in the ground and raised a mound of stone a				
From which: A pine ll in. dia. bears N44°W, 100.5 ft. scribed E 1/16 S A pine l3 in. dia. bears S45°W, 63.9 ft. scribed E 1/16 S 2 Set steel posts with warning and boundary signs 5 ft. North 5 ft. South from corner. Nailed bearing tree signs and bras washers stamped PLS 848 to each tree. Painted red band around each tree.	3 BT. and			
I hereby certify that the above corner monument was established as herein described on 8/12/81.	18			
Witnesses:				
	PROUPOD			
(REGISTERED)	ergoson			
PROFESSIONAL				
LAND SURVEYOR				
Mike Woodward				
Mike woodwar	0			
1 bull martin				
OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848				
Office of Co. Surveyor County of Umatilla				
State of Dr. EDDD				
for record on the. 22 day of January				
David Krumbein by Bith Shetts				
(COUNTY OFFICIAL)				
Form R6-7100-57 (9/71)	ф GPO798-276			

82-01-6

T-2