## History of original corner establishment:

Corner not previously established.

L	AGRAM	1
	T4S	R30E
E	1/16	13 24
		981 5 848

N-23

Description of corner evidence found:

N/A

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stampedaas shown on the diagram. Set 18 inches in the ground and raised a mound of stone around the pipe. From which: A fir 9 inches dia. bears N14°W, 4.5 ft. scribed E 1/16 S 13 BT. A fir 15 inches dia. bears S62°W, 16.5 ft. scribed E 1/16 S 24 BT. Set steel post with warning and boundary signs 5 ft. East and 5 ft. North from corner. Nailed bearing tree signs and brass washers stamped PLS 848

to each tree. Painted red band around each tree.

	Witnesses:	
	D. Mitchell Ferguso	n
PROFESSIONAL		
LAND SURVEYOR	Mike Woodward	
Hant		2
loup from		
OREGON JULY 12, 1988		
DOUGLAS M. FERGUSON 848		
	1 Control 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
Office of CO. SURVEYOR County of	Umatilla	
State of Dregon I hereby certify that the within	n instrument was filed in this office	
for record on the 22 day of January 192	$\frac{12}{51}$	
	S (A) PH	

82-1-0

T-2

\$ GPO-798-276