USDA-FOREST SERVICE GPO 940	•147		1		46
Index File No. P-24	CORNER RECORD		Tract or	Cor.	. '
1 45 R. 30E	R.D. <u>Ukiah</u>	_ County	Survey No Umatilla	No	
Merid. Willamette	N.F. <u>Umatilla</u>	_ State	Oregon		
CORNER DIAGRAM T45 R3DE	DESCRIBE CORNER MONUME	NT FOUND			
143 11302	Corner not pre	viously	established	•	
E 1/16		·			
5 24				•	
N		-			. 2
ĵ 1981	DESCRIBE BEARING TREES O	R OTHER OFFI	CIAL ACCESSORIES	FOUND	
PLS 848	N/A				,
•					
6		•			
PHOTO IDENTIFICATION DATA	`	-			
Photo No.	1.		•	-	
Filed At.			* .	•	3
Object Ident.	DESCRIBE CORNER LOCATION	RELATIVE TO	NEAR-BY FEATURES	, ALSO HOW TO REAC	CH CORNER
Signature 7	Corner on flat	ground	in open pin	e timber.	4.6
PLANE COORDINATE POSITION DATA	Primitive road	approx.	300 ft. No:	rth and	
State Zone	500 ft. South	from cor	ner.		
×			And the second second		
Y			* .		
Estab. By					
Signature	Title Division		quorters	Date 7100	-52 (3, 68)
Marie	PLS 848	Mt. Ver	non, OR	8/13/81	5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" iron pipe with 3" brass cap stamped as shown on the diagram. Set pipe 15 inches in the ground and raised a mound of stone around the pipe.

From which:

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE A pine 12 inches dia. bears N23°E, 107.4 ft. scribed CE 1/16 5 24 BT.

A pine 12 inches dia. bears 51° W, 41.5 ft. scribed CE 1/16 S 24 BT. Set steel posts with warning and boundary sign 5 ft. South

M.

and 5 ft. East from corner.

Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted red band around each tree.

					<u> </u>			10
Wor	k Done By D.M. Ferggs	Surveyor	8/13, Dote	/81 State Region or Agency	istration No. DR	PL5 {	348	
Cert	Neg Cor Record Scaboted 5 J	X No Filed At Un	matilla Co.				-	
	PROFESSIONAL LAND SURVEYOR		tnesses to	above cor	:ner:			•
	OREGON JULY 12, 1968				itchell Fo Woodward	_	חם	

DOUGLAS M. FERGUSON

Tract or Surv. No.

Cor.