USDA-FOREST SERVICE			<del></del>
Index File No. $\triangle - 19$	CORNER RECOR (Ref. FSA	(7151 4) Survey No	Cor
T 45 R. 30E	_R.D. <u>Ukiah</u>	County <u>Umatilla</u>	
Merid. Willamette		StateOregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUN	MENT FOUND	
T45 R30E C 5 1/16 5 23	·	y established.	
) C	DESCRIBE BEARING TREES	OR OTHER OFFICIAL ACCESSORIES	FOUND
1981 PLS 848	N/A	on other contains accessories	FOUND
PHOTO IDENTIFICATION DATA			
Photo No.			
Filed At.	1 -		
Object Ident.	DESCRIBE CORNER LOCATIO	N RELATIVE TO NEAR-BY FEATURE	S ALSO HOW TO REACH CORNER
Ident. By	DErom the C 1/	/ C 35	
PLANE COORDINATE POSITION DATA	I MOTIFIED DE L'US 1	4 Sec. 23, approxima ridge road, go South	1 1/4 mi +c
State Zone	corner. Corn	er is on a South slo	pe in open ground.
<u>x</u> —			
Y			
Estob. By		•	
Signature	Title Divisio	n Headquarters	Date 7100 50 (0 750)
men	PL5 848	Mt. Vernon, DR	/100-52-(3, 68)

.....

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap, stamped as shown on the diagram. Set 12" in the ground and raised a mound of stone around the pipe.

From which: ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A pine 14" dia. bears 582°E, 34.3 ft. scribed C S 1/16 S 23 BT. A pine 10" dia. bears 550°W, 91.4 ft. scribed C 5 1/16 5 23 BT. Set steel posts with warning and boundary signs 10 ft. East and 10 ft. North from corner. Nailed bearing tree tags, brass washers stamped PLS 848 and painted red band around each tree.

							10
Work Done By D.M. Fergusor	<u>Title</u>	Surveyor	7/27/81 	State Registra or Agency	tion No. DR	PLS 848	
Certified CorcRecond Propored ? Yes	X No	Filed At: Umati]	la Co. S	urvevor's	<u>∏f #ate</u>	10/81	
PROFESSIONAL LAND SURVEYOR		REMARKS			·		
lenforten							
OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848	_	Cittan				-	12
Index File No. T.	R.	M.	Tract	or Surv. No.		Cor.	13