## History of original corner establishment:

Corner not previously established.

	DIAGRAM	1
	T45	R30E
E1,	/16_52 52	23
	198 PLS	31 6 848

Description of corner evidence found:

N/A

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 26" in the ground. From which: A fir 16" dia. bears N17°E, 7.2 ft., scribed E 1/16 S 23 BT. A fir 16" dia. bears S33°W, 7.2 ft. scribed E 1/16 S 26 BT. Set steel post with warning and boundary signs 5' N and 5' E from corner. Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted a red band around each tree.

Witnesses:

I hereby certify that the above corner monument was established on 7/27/81 as herein described.

REGISTERED	7
	<u> </u>
LAND SURVEYO	2
1. hur	
buga in far	7
IIII Y 12, 1968	
DOUGLAS M. FERGUSUN	-
	OREGON

D. Mitchell Ferguson

Jeff Smith

Office of County Surveyor	County of Umatilla
State of Oregon / hereby certify the	t the within instrument was filed in this office
for record on the day of	
tor record on the The day of January	Butty Shall
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

0

\$ GPO-798-276

T-2

82-1-B