USDA-FOREST SERVICE		35
Index 5-23 File No. 5-23	CORNER RECORD (SEARCH) Tract or (Ref. FSM 7151.4) Survey No.	Cor.
T 45 R. 30E	R.D. <u>Ukiah</u> County <u>Ilmatilla</u>	No
Merid. Willamette	N.F. Umatilla Stote Oregon	<del></del>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
T45 R30E	Corner not previously established.	
C N W/1615 <b>5</b> 25		
1981	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
PLS 848	' N/A	
PHOTO IDENTIFICATION DATA  Photo No Filed At		
Object Ident Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HE Corner is on open ridge on slight NE s	OW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X	Ridge road approx. 200 ft. North. Corner is visible from the road.	
Estab. By		
Signatore Signatore	Title Division Headquarters Date PLs 848 Mt. Vernon, DR 7/28/	7100-52 (3, 68) 81

## CORNER RECORD (PERPETUATION)

MONUMENT DESCRIPE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the
diagram. Set pipe 12 inches in the ground and raised a mound of stone
around the pipe.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No bearing trees available Set steel posts with warning and boundary signs 5 ft. South and 5 ft. East from corner.

M.

DOUGLAS M. FERGUSON

					10
Work Done By D.M. Fer	quson title Surveyor	7/28/8: Dote	State Registration or Agency	on No. OR P	LS 848
Certified Cor. Record Prepured	1 ? Yes X No Filed At: Uma	tilla Co.SO:	everor Off	• Date	. 11
PROFESSIONAL	REMARI	(S		· ·	
LAND SURVEYOR	Witnesse:	s to above o			
In Mita			IYI	ike Woodw	ord
OREGON JULY 12, 1968					

Tract or Surv. No.

Cor.