History	of	original	corner	establishment:

Corner not previously established.

DIAGRA	554D	
T45		30E
E	1/16	ō
С	20	C
S	25	
19	981	
	5 848	3
		-
		-
T -	24	

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the		
original location of this corner:		
Set 3"x30" galv. iron pipe with 3" brass cap stamp diagram. Pipe set 6 inches in the ground and rai around the pipe.	ed as shown sed a mound	on the of stone
From which: A pine 10 inches dia. bears S61°W, 118.2 ft. scri No other tree available. Set steel posts with warning and boundary signs 6 and 8 ft. East from corner. Nailed bearing tree sign and brass washer stamped Painted a red band around the tree.	ft. North	
I hereby certify that the above corner monument was established as herein described on 7/29/81.		
Witnesses		
REGISTERED PROFESSIONAL LAND SURVEYOR		1 Ferguson
The	Mike Woodu	ard
OREGON JULY 12. 1968 DOUGLAS M. FERGUSON 848		
Office of	nd in this office	

Form R6-7100-57 (9/71)

\$ GPO-798-276

82-01-C

T-2