History of original corner establishment:

Corner not previusly established.



Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram Set pipe 26 inches in the ground.

From which:

A pine 12 inches dia. bears N51°W, 53.8 ft. scribed CS 1/16 S 25 BT. A pine 13 inches dia. bears S88°E, 7.7 ft. scribed CS 1/16 S 25 BT. Set steel posts with warning and boundary signs 5 ft. South and 5 ft. West from corner. Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted red band around each tree.

I hereby	certi	lfy	that	the	abov	e corne	r
monument	was e	esta	ablish	ned a	as he	rein	
described	, on	7/3	30/81.	i i			

Witnesses: D. Mitchell Ferguson

Mike Woodward

PROFESSIONAL LAND SURVEYOR OREGON JULY 12, 1968 DOUGLAS M. FERGUSON 848

REGISTERED

Office of CO. Surveyor County of Umatilla State of Bregon I bereby certify that the within instrument was filed in this office for record on the I'd day of Danuary 1822 Daniel Mumblem by Betty Shall State of. Oregon itto (COUNTY OFFICIAL) (DEPUTY)

87-01-C

Form R6-7100-57 (9/71)

\$ GPO-798-276