CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: No corner was originally set.

Index File DIAGRAM	
T5N	R38E
$\frac{1}{16}$ $\frac{1}{80}$	S4

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set 1"x30" galvanized pipe with 3" brass CROWN ZELLER BACH cap stamped:

Set pipe 20" in ground with mound of stone to cap. Bearing trees:

A Spruce 5" dia bears N45°E 28.4 ft scribed C1/16 80 S4 BT. A Spruce 8" dia bears N74°W 57.8 ft scribed C1/16 80 S4 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.



I hereby certify the above corner monument was established as herein described on Sept. 23, 1980.

R38E

S4

Witnesses: R. Orton

T5N

1

80

°R PLS 1294

G. Wagoner

L. Huntsman

A. Hanley

Office of County Surveyor	County of
State of Oregon , / hereby certify	that the within instrument was filed in this office
for regord on the day of Alecent	Bitter Shatts
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276

R-186-B