## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: No corner was originally set.

T5N	R38E
Cla	S4

Description of corner evidence found:

## Description of monument and accessories I established to perpetuate the

original location of this corner: At surveyed point set 1"x30" galvanized pipe with 3" brass cap stamped: Set pipe 24" in ground from which: Set pipe 24" in ground from which:

Set pipe 24" in ground from which:<br/>A White Fir 21" dia bears N39°E 55.3 ft. scribed:  $C_4$  S4 BT.T5NR38EA White Fir 15" dia bears S34°E 43.6 ft scribed:  $C_4$  S4 BT. $C_4$  S4 BT. $C_4$  S4 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washers stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.



I hereby certify the above corner monument was established as herein described on Sept. 19, 1980.

Witnesses: R. Orton G. Wagoner

L. Huntsman

A. Hanley

. .....

Office of County Surveyor	County of Umatilla
State of Oregon , I hereby certify the for second on the day of Secondary David Printing by	at the within instrument was filed in this office
Parie Premitien	Bith L. The
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276

R-186-B