History of original corner establishment: In August 1899, under GLO Contract No. 699, William E. Campbell set basalt stone $15"\times10"\times10"$ ins. 6 ins. in the ground, place mound of stone firmly about corner, for $\frac{1}{4}$ sec cor. marked $\frac{1}{4}$ on N. face from which a Fir 17" dia. bears N19°E 53 lks dist. marked $\frac{1}{4}$ S4BT. A Fir 14" dia. bears S53 $\frac{1}{4}$ °W, 88 lks dist. marked $\frac{1}{4}$ S9 BT.

Ir	ndex File	No. E-11
	DIAGRAM	
	T5N	R38E
	14 - St	4 9

Description of corner evidence found: A corner location found 12"x10"x10"stone lying on the ground in mound of stone with "14" visible on North face. Could find no trace of original BT's.

Description of monument and accessories I established to perpetuate the

original location of this corner: In place of stone set 1"x30" galvanized pipe with 3" brass cap stamped: Set pipe 22" is stamped to the state of the stone set 1"x30" galvanized pipe with 3" brass cap $X ELLERBAC_{y}$

Set pipe 22" in ground with original stone buried alongside and mound of stone to cap. Bearing trees: 200^{1/1} 54 59 7.57 1980 R.38E LIC. 1294

A White Fir 9" dia bears N42⁰W, 52.0 ft. scribed ½ S4 BT A White Fir 8" dia bears S74⁰W, 57.3 ft. scribed ½ S9 BT

Attached 54-3 and 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red.



I hereby certify the above corner monument was reestablished as herein described on Sept. 10, 1980.

Witnesses: R. Orton M. Wagoner

Office of County Surveyor	County of Umatilla
State of Oregon / hereby certify	that the within instrument was filed in still
for record on the dey of here mit	y Butting that a the
(COUNTY OFFICIAL)	DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276